

## Sägengewinde DIN 513 (Regelgewinde)

Gewinde- Nenn Durchmesser	Durchmesser Bolzen mm	Durchmesser Kernloch Mutter mm
S 10 x 2	6,528	7,000
S 12 x 3	6,794	7,500
S 14 x 3	8,794	9,500
S 16 x 4	9,058	10,000
S 18 x 4	11,058	12,000
S 20 x 4	13,058	14,000
S 22 x 5	13,322	14,500
S 24 x 5	15,322	16,500
S 26 x 5	17,322	18,500
S 28 x 5	19,322	20,500
S 30 x 6	19,586	21,000
S 32 x 6	21,586	23,000
S 34 x 6	23,586	25,000
S 36 x 6	25,586	27,000
S 38 x 7	25,852	27,500
S 40 x 7	27,825	29,500
S 42 x 7	39,825	31,500
S 44 x 7	31,825	33,500
S 46 x 8	32,116	34,000
S 48 x 8	34,116	36,000
S 50 x 8	36,116	38,000
S 52 x 8	38,116	40,000
S 55 x 9	39,380	41,500
S 60 x 9	44,380	46,500
S 65 x 10	47,644	50,000
S 70 x 10	52,644	55,000
S 75 x 10	57,644	60,00
S 80 x 10	62,644	65,000
S 85 x 12	64,174	67,000
S 90 x 12	69,174	72,000
S 95 x 12	74,174	77,000
S 100 x 12	79,174	82,000

